IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
DAVID S. BONALLE ET AL.	Examiner: Nam V. Nguyen
Appl. No.: 10/810,469	: Art Unit: 2612)
Filed: March 27, 2004	: Conf. No.: 9765
For: SYSTEMS AND METHODS FOR PROVIDING A RF TRANSACTION DEVICE OPERABLE TO STORE MULTIPLE DISTINCT CALLING CARD ACCOUNTS) :) :)) :
U.S. Patent No.: 7,463,133 B2	·)
Issued: December 9, 2008) November 2, 2009

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

The amount of \$100.00 to cover the statutory fee for such Certificate of Correction is being paid concurrently; please charge any deficiency in this fee, and credit any overpayment, to Deposit Account 06-1205.

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Jonathan Berschadsky

Attorney for Patentees Registration No. 46,551

FITZPATRICK, CELLA, HARPER & SCINTO 1290 Avenue of the Americas New York, New York 10104-3800

Facsimile: (212) 218-2200

FCHS_WS3975013 v1

Stable Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 7,463,133 B2

DATED

December 9, 2008

INVENTOR(S) :

DAVID S. BONALLE ET AL.

Page 1 of 10

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

[56] REFERENCES CITED:

U.S. Patent Documents

"4,639,765 A 1/1987 dHont" should read --4,639,765 A 1/1987 D'Hont--.

"5,247,304 A 9/1993 dHont" should read --5,247,304 A 9/1993 D'Hont--.

"5,274,392 A 12/1993 dHont" should read --5,274,392 A 12/1993 D'Hont--.

"5,351,052 A 9/1994 dHont" should read --5,351,052 A 9/1994 D'Hont--.

"5,373,303 A 12/1994 dHont" should read --5,373,303 A 12/1994 D'Hont--.

"5,408,243 A 4/1995 dHont" should read --5,408,243 A 4/1995 D'Hont--.

"5,428,363 A 6/1995 dHont" should read --5,428,363 A 6/1995 D'Hont--.

"5,453,747 A 9/1995 dHont" should read --5,453,747 A 9/1995 D'Hont--.

"5,491,483 A 2/1996 dHont" should read --5,491,483 A 2/1996 D'Hont--.

"5,497,121 A 3/1996 dHont" should read --5,497,121 A 3/1996 D'Hont--.

"5,557,279 A 9/1996 dHont" should read --5,557,279 A 9/1996 D'Hont--.

"5,563,582 A 10/1996 dHont" should read --5,563,582 A 10/1996 D'Hont--.

"5,592,150 A 1/1997 dHont" should read --5,592,150 A 1/1997 D'Hont--.

"5,594,448 A 1/1997 dHont" should read --5,594,448 A 1/1997 D'Hont--.

"5,619,207 A 4/1997 dHont" should read --5,619,207 A 4/1997 D'Hont--.

"5,625,366 A 4/1997 dHont" should read --5,625,366 A 4/1997 D'Hont--.

"5,625,370 A 4/1997 dHont" should read --5,625,370 A 4/1997 D'Hont--.

"5,625,695 A 4/1997 MRaihi" should read --5,625,695 A 4/1997 M'Raihi--.

"5,732,579 A 3/1998 dHont" should read --5,732,579 A 3/1998 D'Hont--.

"5,748,137 A 5/1998 dHont" should read --5,748,137 A 5/1998 D'Hont--.

"5,867,100 A 2/1999 dHont" should read --5,867,100 A 2/1999 D'Hont--.

"5,870,915 A 2/1999 dHont" should read --5,870,915 A 2/1999 D'Hont--.

"5,955,969 A 9/1999 dHont" should read --5,955,969 A 9/1999 D'Hont--.

"6,064,320 A 5/2000 dHont" should read --6,064,320 A 5/2000 D'Hont--.

"6,226,382 B1 5/2001 MRaihi" should read --6,226,382 B1 5/2001 M'Raihi--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 1290 Avenue of the Amerivas

New York, New York 10104-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

PATENT NO. <u>US 7,463,133 B2</u>

No. of add'l. copies @ 30¢ per page



Form PTO 1050 (Rev. 3-82)

FCHS WS3975013v1

Stable Here Ould ININER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 7,463,133 B2

DATED

December 9, 2008

INVENTOR(S) :

DAVID S. BONALLE ET AL.

Page 2 of 10

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

[56] REFERENCES CITED:

U.S. Patent Documents

"2003/0025600 A1 2/2003 Blachard" should read --2003/0025600 A1 2/2003 Blanchard--.

"2003/0225716 A1 12/2003 Atkinson et al." should read --2003/0225716 A1 12/2003 Atkinson et al.--.

[56] REFERENCES CITED:

Foreign Patent Documents

"EP 0358525 3/1990" should be deleted.

"EP 1016947 7/2000" should be deleted.

"GB 2347537 9/2000" should be deleted.

"JP 2000-11109 A 1/2000" should be deleted.

"JP 2000015288 A 1/2000" should read --JP 2000-015288 A 1/2000--.

"JP 2000-40181 A 2/2000" should be deleted.

"JP 2000067312 A 3/2000" should read --JP 2000-067312 A 3/2000--.

"JP 2000207641 A 7/2000" should read --JP 2000-207641 A 7/2000--.

"JP 2001-5931 A 1/2001" should be deleted.

"JP 2001283122 A 10/2001" should read --JP 2001-283122 A 10/2001--.

"WO 95/32919 12/1995" should be deleted.

"WO 99/03057 A1 1/1999" should be deleted.

"WO 00/10144 A1 2/2000" should be deleted.

"WO 00/38088 A1 6/2000" should be deleted.

"WO 01/04825 A1 1/2001" should be deleted.

"WO 01/15098 A1 3/2001" should be deleted.

"WO 01/43095 A2 6/2001" should be deleted.

"WO 01/72224 A1 10/2001" should be deleted.

"WO 01/77856 A1 10/2001" should be deleted.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

1290 Avenue of the Amerivas

New York, New York 10104-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

PATENT NO. <u>US 7,463,133 B2</u>

No. of add'l. copies @ 30¢ per page



Stable Only! PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 7,463,133 B2

DATED

December 9, 2008

INVENTOR(S) :

DAVID S. BONALLE ET AL.

Page 3 of 10

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

[56] REFERENCES CITED:

Foreign Patent Documents

"WO 01/80473 A2 10/2001" should be deleted.

"WO 01/90962 A1 11/2001" should be deleted.

"WO 01/95243 A2 12/2001" should be deleted.

"WO 02/01485 A1 1/2002" should be deleted.

"WO 02/13134 A2 2/2002" should be deleted.

"WO 02/063545 A2 8/2002" should be deleted.

"WO 02/065246 A2 8/2002" should be deleted.

"WO 02/065404 A2 8/2002" should be deleted.

"WO 02/069221 A1 9/2002" should be deleted.

"WO 02/073512 A1 9/2002" should be deleted.

"WO 02/086665 A2 10/2002" should be deleted.

"WO 02/091281 A2 11/2002" should be deleted.

"WO02/097575 A2 12/2002" should be deleted.

"WO 02/101670 A2 12/2002" should be deleted.

[56] REFERENCES CITED:

Other Publications

"BobBrewin" should read -- Bob Brewin--.

"Mobile Speedpass" should read -- Mobil Speedpass--.

"Spot Technology" should read --SPOT Technology--.

"Microsft" should read -- Microsoft --.

"See Spot Run" should read -- See SPOT Run--.

"Microsoft Spot" should read -- Microsoft SPOT" ---.

"RFID Journnal." should read -- RFID Journal, --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 1290 Avenue of the Amerivas New York, New York 10104-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

PATENT NO. <u>US 7,463,133 B2</u>

No. of add'l. copies @ 30¢ per page

 \Rightarrow

FCHS_WS3975013v1

Staple Here Only! Staple Here Unly! Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 7,463,133 B2

DATED

December 9, 2008

INVENTOR(S) :

DAVID S. BONALLE ET AL.

Page 4 of 10

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

[56] REFERENCES CITED:

Other Publications

"card the uses" should read --card that uses--.

"to able" should read --to be able--.

Physical Reality: A Second Look", Ken Sharp, Senior Technical Editor,

http://www.idsystem.com/reader/1999_03/phys0399_pt2/phys0399_pt2.htm.

"Magic Wands' to Speed Mobile Sales", Bob Brewin, Jan. 15, 2001,

http://www.computerworld.com/mobiletopics/mobile/story/1,10801,563300.ht

ml. Functional Specification, Standard Card IC MF1 1C S. 50, Philips

Semiconductors, Product Specification Rev. 5.1 May 2001." should be deleted.

"FTC Suite Against" should read -FTC Suit Against--.

"The Institution of Electrical Engineers," should read -- The Institute of Electrical and Electronics engineers (IEEE),--.

[74] ATTORNEY:

Attorney, "Fitpatrick, Cella, Harper & Scinto" should read --Fitzpatrick, Cella, Harper & Scinto--.

SHEET 1

Figure 1, "Modity" should read --Modify--.

SHEET 4

Figure 4, "Creat" should read -- Create--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 1290 Avenue of the Amerivas New York, New York 10104-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

PATENT NO. <u>US 7,463,133 B2</u>

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 7,463,133 B2

DATED

December 9, 2008

INVENTOR(S) :

DAVID S. BONALLE ET AL.

Page 5 of 10

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 2

Line 14, "stolen preventing" should read --stolen, preventing--.

COLUMN 3

Line 67, "system" should read --system.--.

COLUMN 6

Line 27, "links. For" should read --links: for--.

COLUMN 8

Line 5, "instrument" should read --instruments--; and Line 39, "Bishop, et. al.," should read --Bishop et al.,--.

COLUMN 9

Line 14, "type and etc." should read --type, etc.--; and Line 31, "instrument," should read --instrument--.

COLUMN 10

Line 13, "DB2by" should read --DB2 by--; and Line 47, "software;" should read --software,--.

COLUMN 11

Line 65, "where" should be deleted.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 1290 Avenue of the Amerivas New York, New York 10104-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. US 7,463,133 B2

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

FCHS WS3975013v1



Stable Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 7,463,133 B2

DATED

December 9, 2008

INVENTOR(S) :

DAVID S. BONALLE ET AL.

Page 6 of 10

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 12

Line 43, "stand-alone" should read --stand-alone device--.

COLUMN 13

Line 21, "stand-alone" should read --stand-alone device--;

Line 29, "merchant" (first occurrence) should read --the merchant--; and

Line 51, "indicting" should read --indicating--.

COLUMN 14

Line 37, "provide the to a" should read --provide the data to a--.

COLUMN 15

Line 10, "stand-alone" should read --stand-alone device--;

Line 48, "indicates" should read -- and indicates --; and

Line 51, "indicting" should read --indicating--.

COLUMN 16

Line 19, "system. 220," should read --system 220,--.

COLUMN 17

Line 57, "a issuer" should read --an issuer--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

1290 Avenue of the Amerivas

New York, New York 10104-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

PATENT NO. <u>US 7,463,133 B2</u>

No. of add'l. copies @ 30¢ per page



Staple Here Only! WINE S. WINE LANGE LANGE

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 7,463,133 B2

DATED

December 9, 2008

INVENTOR(S) :

DAVID S. BONALLE ET AL.

Page 7 of 10

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 18

Line 36, "data sets in similar" should read --data sets proceeds in a similar--; and Line 60, "interaction" should read --and interaction--.

COLUMN 19

Line 16, "issuer-owning" should read --issuer owning--; and Line 55, "system. 230." should read --system 230.--.

COLUMN 20

Line 5, "DB2by" should read --DB2 by--;

Line 29, "invention," should read --the invention,--;

Line 33, "sets to-the" should read --sets to the--; and

Line 47, "device" (first occurrence) should be deleted.

COLUMN 21

Line 31, "the steps of loading" should read -- the steps of: loading--.

COLUMN 22

Line 61, "the like: for" should read --the like. For--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 1290 Avenue of the Amerivas New York, New York 10104-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. <u>US 7,463,133 B2</u>

No. of add'l. copies @ 30¢ per page



Form PTO 1050 (Rev. 3-82)

Staple Here Only! NINE NINE NINE

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 7,463,133 B2

DATED

December 9, 2008

INVENTOR(S) :

DAVID S. BONALLE ET AL.

Page 8 of 10

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 24

Line 27, "system 230. (step" should read --system 230 (step--;

Line 31, "to the inter-" should be deleted;

Line 32, "action device 290" should be deleted; and

Line 45, "may the present" should read --may present--.

COLUMN 26

Line 15, "processor 804: Main" should read --processor 804. Main--; and Line 21, "ink 803 the" should read --ink 803. The--.

COLUMN 27

Line 13, "from. LEC" should read --from LEC--.

COLUMN 28

Line 56, "and or unique" should read --and/or unique--.

COLUMN 30

Line 12, "rated antenna" should read --rated, antenna--;

Line 22, "transact-" should read --transact--;

Line 33, "REID reader" should read -- RFID reader--; and

Line 48, "REID reader" should read -- RFID reader--.

COLUMN 31

Line 46, "as whether" should read --as to whether--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 1290 Avenue of the Amerivas

New York, New York 10104-3800

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

PATENT NO. US 7,463,133 B2

No. of add'l. copies @ 30¢ per page



FCHS WS3975013v1

Stable Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 7,463,133 B2

DATED

December 9, 2008

INVENTOR(S) :

DAVID S. BONALLE ET AL.

Page 9 of 10

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 32

Line 7, "which. HSS" should read --which HSS--; and Line 66, "message HSS" should read --message to HSS--.

COLUMN 33

Line 51, "medium Any" should read --medium. Any--.

COLUMN 34

Line 20, "appended and" should read --appended claims and--;

Line 53, "carrier set" should read --carrier data set--; and

Line 67, "format." should read --formats.--.

COLUMN 35

Line 23, "comprising" should read --comprising:--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 1290 Avenue of the Amerivas New York, New York 10104-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

PATENT NO. <u>US 7,463,133 B2</u>

No. of add'l. copies @ 30¢ per page

 \Box

Form PTO 1050 (Rev. 3-82)

FCHS_WS3975013v1

Staple Here Only! WILL SABUNIERS

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

US 7,463,133 B2

DATED

December 9, 2008

INVENTOR(S) :

DAVID S. BONALLE ET AL.

Page 10 of 10

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 36

Line 15, "set;" should read --set; and--;

Line 18, "format." should read --formats.--; and

Line 19, "7. system" should read --7. A system--.

FCHS_WS 3975013v1

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 1290 Avenue of the Amerivas New York, New York 10104-3800 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. <u>US 7,463,133 B2</u>

No. of add'l. copies @ 30¢ per page

 \Box

Form PTO 1050 (Rev. 3-82)

FCHS_WS3975013v1